

Hollands Park Wall Replacement Wall Project Update 1



21/06/2023

As you can see from this photo, we have managed to take down a large section of the boundary wall.

Sadly, the old wall was not securely connected to the foundations, so the base layer came away with the wall so it could not be used as a curb.

The ground behind the wall has now been sloped back, leaving the wall foundation exposed.

A new curb will be installed where the current foundations are.

The next step will be the installation of the fence at the top of the slope, which will provide the safety barrier missing from this area for many years.